

Pictures and description of 1999 Four Winds Camper

- #1) Full view (left)
- #2) Engine
- #3 Full view (right) has an awning. But it has about 4 ½ cm holes that need to be repaired. All mechanisms work fine
- #4) Rear View
- #5) Back bedroom (Queen size bed)
- #6) TV in Back Bedroom
- #7) Bathroom Shower
- #8) Bathroom Toilet & Sink
- #9) Hallway and closet
- #10) Refrigerator and Freezer
- #11) Oven, Range and Microwave
- #12) Kitchen Sink (Has a leak in the faucet and under in the fresh water supply)
- #13) Dining Area (converts to bed)
- #14) Couch (converts to bed)
- #15) TV and Single Bunk bed. (Bunk bed pulls out)
- #16) VCR, DVD
- #17) Extra Chair
- #18) Cab
- #19) Tires have extensions for ease of checking and adding air
- #20) Has a Satellite dish
- #21) Generator (Onan Microlite 4000 (Has a brand new Stator but may need a fuel pump)
- Things that need fixing...
- #22) Steps (need replacing)
- #23) Needs an exterior cover for the radio
- #24) Needs bottom panels re-screwed and sealed
- #25) Ladder needs work or new one installed
- #26) Needs a new fuel door
- #27) Could use a new counter top